CHAINS

## RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 13 and 24, T.2S, R.7W., W.M., Tillamook County, Oregon.

## ORIGINAL

Post, (now missing), L.H.L. Lumber Corp. 3/4" iron pipe and cap found in place, from which a:

14" Hemlock bears S81°W 45 lks.; now 15" uproot, part of scribes BT remaining, root hole in place.

9" Hemlock bears S51°E 36 lks.; now 9" uproot, badly rotted, root hole in place.

## RESTORED

Drove above 3/4" galvanized iron pipe with 2½" bronze cap marked "L.H.L. Lumber Corp. ½ cor. 13,24,T2S R7W 1954", into within 3 inches of ground, in mound of stone, and from which a:

46" Fir stump bears S25°W 15.6 ft.; scribed \(\frac{1}{4}\) S24 BT RE 2311. 54" Fir stump bears N53°E 40.2 ft.; scribed \(\frac{1}{4}\) S13 BT.

Set 3"x3"x72" white painted Cedar post 2 ft. SW of pipe.

Oregon State Board of Forestry metal location poster on
54" Fir stump BT.

Also poster on 3"x3"x72" white painted Cedar post 1050 ft.

Dated May 17, 1955.

Restored by Avall & Subsan under my direction.
Arnold G. Gibson, Assistant Engineer



Present and witnessed by Richard Morris
Lloyd Geraths
Robert Sturm

East on South edge R.R. grade.