

CHAINS

Restored Corners: Page ( 112 )

2.

Section Corner  $\frac{9}{16} \times \frac{10}{15}$  T3N, R10W, W.M.

Original by J.C. Hadley; Contract # 183 1873!

Post, From which,

40" Fir N70°E 20 Lks.

50" Fir N10°W 20 "

24" Hemlock S45°E 30 Lks.



No evidence of this corner was found on June 20, 1893 by Manius Buchanan who set the corner described below:

30" Hemlock scribed T3N 510 NE Face  
 R10W 515 SE "  
 516 SW "  
 59 NW "

From which:

4" Hemlock N37°E 60 Lks. Not Found.

Restored Corner:

3/4" x 30" GI pipe set 10 Ft. West of the original Hemlock stump, which is rotted down below the scribed Faces. Several Cruiser marks nearby.

scribed an 8" Hemlock S98T E, N87°W. Ap. 50° Ft.

This corner is at the intersection of blazed lines to the East, West and north.

Running North along a blazed line leading to the 1/4 5 9 and 10.!

Original Notes, Buchanan.

My distances:

18.00 <sup>1186°</sup> Creek 21ks wide SE

1163? Ft.

20.10 <sup>1326°</sup> " 8 " " SE

1327 1/2 "

26.91 <sup>1760°</sup> Cedar Line tree 2 Notches on N & S Faces.

1776° " stumps

April 4, 1951.

blown out for Road  
 Roots in place.