

CHAINS

3.

Restored Corners:

Page ( 113 )

Section Corner  $\frac{15}{22} | \frac{14}{23}$  T3N, R10W, W.M.  
original!

A post

Found post lying near an iron pipe set for corner presumably by County surveyor. scribe MKs visible.

From which,

126" spruce N87°E 15 LKs stamp in place N87°E 10° Ft  
No scribe marks visible  
4" Vine Maple S13°W 23 LKs gone  
16" Hemlock N53°W 43 LKs Rotted down. No scribes.

Restored Corner:

Left iron pipe in place

From which,

24" spruce N37°W 21° Ft scribed 315 BT E  
12" Hemlock S40°W 77½ Ft. " 372 BT E

Running West from this corner, Failed to find any evidence of original line or the 1/4 S corner of 15 and 22 or the section

Corner  $\frac{14}{21} | \frac{15}{22}$ .

Mar 27, 1951

