

CHAINS

4.

Restored Corners:

Page (114)

section corner $\frac{20}{21} / \frac{29}{28}$ T 3N, R 10W, W.M.

Original:

Post. gone.

From which,

- 16" spruce N40°E 38 Lks
- 40" Hemlock 558°E 71 "
- 96" spruce 348°W 17 "
- 96" spruce N10°W 6 "

gone
 stump in place. No MKs.
 stump " " " "
 " " " a portion
 of original scribe MKs
 plainly visible.

This corner restored in proper position by
 County Surveyor.

Quarter section corner $\frac{21}{28}$ T 3N, R 10W, W.M.

Original:

39.60 Post For 1/4s.
 From which,

In place. spruce knot, scribe
 Marks plainly visible

- 6" Barberrry N8°E 60 Lks
- 5" Elder N9°W 70 "

gone.
 gone.

Restored corner:

Left original post in place. still in good
 condition, From which,

- 18" spruce 324°W 17 1/2' scribed 1/4s E
- 18" spruce N45°W 16 1/2' " 1/4s E

Feb 3, 1951

BOOK 2

