

CHAINS

T6S R11W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

T5-6S, R11W, Section corner common to Secs 1-2-35-36, W.M., Tillamook County, Oregon

Original monument: Post

Original witnesses:

- A spruce, 9" diam., bears N.38°W., 31 lks. dist.
- A spruce, 5" diam., bears N.59°E., 31 lks. dist.
- A spruce, 8" diam., bears S.68°E., 15 lks. dist.
- A hemlock, 6" diam., bears S.11°W., 14 lks. dist.

Found 3" x 3" wood stake 8" above ground in poor condition with mks rotted away. Found small knots on post cut off by axe. In my opinion this is a remnant of the original post.

Found 33" spruce stub, S.74°E., (not 68°E., as in orig. notes) 15 lks. with visible mks S1.

Found 18" rotted hemlock stub, S.7°W. (not S.11°W., as in orig. notes) 14 lks. with visible mks "BT".

The N.W. and N.E. BT^s are gone.

I set 1½" galv. pipe 5 ft. above ground.

I mark New BT^s

- 6" hemlock, N.31° 30'W., 39 lks. mkd T4SR11WS35 BT.
- 4" hemlock, N.7°E., 16 lks. mkd X BT. - one foot above ground.
- 43" spruce, S.30°W., 39 lks. mkd T6SR11WS2 BT.

By Leonard Whitmore, Tillamook County Dep. Surveyor. 9-6-65

Witnessed by: M. Whitmore
Lester Fultz

35 | 36
2 | 1