

CHAINS

Page 13.

EVALUATION AND RESTORATION OF LAND SECTION CORNERS
T4SR9W

28
33

Standard section corner between secs. 28-33
east boundary.
Original Monument
3x3 post

Original Witness
48" fir, N.86°W., 86 Lks.
36" fir, S.26°W., 148 Lks.
48" fir, S.56°E., 94 Lks.
40" fir, N.42°E., 60 Lks.

I found 36" snag, S.26°W., 96ft. with face showing axe marks but all marks are rotted away. The original NW, NE, and SE BTs are in their recorded bearings and distances but all marks are rotted away. This corner point corresponds with the recorded distance of 92.4ft. south of a creek running NW. I set 6"x2" pitch post 2ft. above ground Mkd. S28 on NW. and S33 on SW sides.

I marked 2 new Bts:
14" alder, N.81°W., 55ft. Mkd S28 BT
16" alder, S.43°30'W., 17½ft. Mkd S33 BT

Witness: M. Whitmore
by Leonard Whitmore,
Tillamook County deputy Surveyor
3-19-62

T4SR9W

29 | 28

Standard section corner between secs;
28-29 N. boundary.
Original Monument
3x3 post

Original Witnesses:
30" fir, N.36°W., 57 Lks.
30" fir, N.31°E., 58 Lks.
36" fir, S.37°W., 87 Lks.
30" fir, S.28°E., 60 Lks.

I found the original fir post standing in a rock mound. Found 36" snag, S.37°W., 87 Lks. with the scribing burned off. Found 30" snag, S.28°E., 60 Lks. with the scribing burned off. Found axe marks on the NE and NW BT snags where a later surveyor destroyed the marks on these snags.