

County Surveyor's Record, Tillamook County, Oregon

CHAINS

Restoration of the corner common to Sections 34 and 35, T2S, R10W, and Section 3, T3S, R10W, W.M.

Original corner was set in 1882 while running West on the Township line. "Set post for corner to Sections 34, 35, 3 and 2 from which:

- 16" Hemlock bears N 53° W 44 lks
- 16" Hemlock bears N 38° E 32 lks
- 12" Hemlock bears S 13° E 75 lks
- 40" Hemlock bears S 30° W 34 lks"

On May 8, 1969, I found the 16" Hemlock, bearing N 53° W (now a rotting stump) with incomplete scribe marks visible. The 16" Hemlock bearing N 38° E and 40" Hemlock (also rotting stumps) are properly located in relation to the corner but no face or marks are found.

From these original bearing trees I set a 3/4 iron pipe with 3 inch brass cap for the corner to Sections 34 and 35, T2S, R10W, on the township line between T2S and T3S, R10W, W.M. I marked new bearing trees as follows:

- 14" Hemlock bearing N 44° E 52.1 feet, scribed "BT-S35-T2S"
- 12" Spruce bearing N 43° W 14.8 feet, scribed "BT-S34-376"
- 10" Spruce bearing S 46° W 14.3 feet, scribed "BT-S3-T3S, R10W"

Charles G. Collard

By: Charles G. Collard
Registered Land Surveyor
Oregon #376

Witnesses: G. W. Jaques
B. K. Conrad

May 8, 1969