

T3N, R9W, SECTION CORNER, SE Corner Section 13,
NE Corner, Section 24.

NOTICE OF RE SET CORNER.

On October 6, 1966, I re set the corner marker which had accidentally been bulldozed out of position. The corner marker consists of a standard OSBF bronze disc, on a galvanized iron pipe 1 1/2" x 3' dated 1952 and with Number 2311; a OSBF metal location poster, on 24" hemlock, bears marks:

" Section Corner $\frac{13}{24}$ T3N, R9W.

S 30 E 12.5 ft. "

I set the marker at this bearing and distance from the metal sign, 2 feet deep in ground, with a mound of rocks to top of pipe, in presence of Wendell Scovell of Nehalem.

W. A. Markham

W. A. Markham
Registered Engineer No. 1842.



AS

BOOK 3

BOOK 3