

CHAINS

Page 2. cont. T.3S.R.8W

Witnesses:

Mervin Whitmore

Daryl Whitmore

by Leonard Whitmore, Tillamook Co. Deputy Surveyor
11-30-63

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

T.3S.R.9W

$\frac{1}{4}$
3 2

$\frac{1}{4}$ corner between secs. 2-3
Original Monument
4" x 4" post

Original Witnesses:

6" fir, S.15°W., 21 $\frac{1}{2}$ Lks. Mkd. $\frac{1}{4}$ S. BT

10" alder, S.70°30'E., 28 Lks. Mkd. $\frac{1}{4}$ S.BT

The post is gone.

I found 19" alder, S.70°30'E., 18 $\frac{1}{2}$ ft. with visible marks $\frac{1}{4}$ SBT.

I found 8" rotted fir log lying upon the ground, S.15°W., 14ft.

to its base. A snag had fallen many years ago knocking this BT to

the ground. All marks are rotted off. I set 1" yellow pipe 36"

above ground. This corner is located on a 50% S.E. slope. A

high ridge running E.-W. is 6 chains to the north.

I marked 2 new BTs:

21" fir, S.28°W., 3 $\frac{1}{2}$ ft. Mkd. $\frac{1}{4}$ S.3BT CS

20" fir, S. 4°E., 10 $\frac{1}{2}$ ft. Mkd. $\frac{1}{4}$ S2BT CS

Witness: Hobart Means

by Leonard Whitmore

Tillamook Co. Deputy Surveyor.

8-26-66

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

T.3S.R.10W.

$\frac{1}{4}$
8
17

$\frac{1}{4}$ Corner between secs. 8-17
Original Monument 6"x 6" post
Original witnesses:

18" hemlock, S.5°W., 17 Lks. Mkd. $\frac{1}{4}$ SBT

16" hemlock, N.27°E., 44Lks. Mkd. $\frac{1}{4}$ SBT

BOOK 3