

County Surveyor's Record, Tillamook County, Oregon

CHAINS

$\frac{1}{4}$
 10 | 11

6S R10W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

One-quarter Corner common to Sections 10-11, W.M.,
Tillamook County, Oregon

ORIGINAL: Albert P. Wilson, Deputy Surveyor, June 25, 1890

Set post, 4" sq., 4' long, 24" in ground, for $\frac{1}{4}$ sec. cor.
mkd. $\frac{1}{4}$ S on W, from which:

A hemlock, 12" diam., bears S25E, 23 lks, mkd

$\frac{1}{4}$ SBT
A fir, 16" diam, bears S32W, 28 lks, mkd $\frac{1}{4}$ SBT

FOUND:

A remnant of the original post in a rotted condition.
At the corner point I found a stone implanted beneath
the surface of the ground.
26" hemlock, S25°E, 15.2 feet with a scribe mark "5"
showing in a parial healed face.
The SW BT lying across a ravine in a rotted condition.
At the uphill side of the stone a remnant of the original
post is found extending 18" into the ground.

RESTORED:

I set a 3" x 3" spruce limb mkd. S10 on W and S11 on
E sides.

I mark one new BT:

30" Spruce, North 46°W., 30 feet mkd. $\frac{1}{4}$ S10BT

RESTORED BY:

Leonard Whitmore, Till. Co. Deputy Surveyor

WITNESSED BY:

H. Means
G. Tilton


Dated: 9-27-67

County Surveyor's Record, Tillamook County, Oregon

CHAINS

THE NO. _____ Survey No. _____
 T 65 R 10W R.D. Hebo County TILLAMOOK
 Merid. Will. N.F. SIUSLAW State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND
 FOUND A REMNANT OF THE ORIG. POST IN A ROTTED
 CONDITION. AT THE CORNER POINT I FOUND A
 STONE IMPLANTED BENEATH THE SURFACE OF THE
 GROUND. See Below

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 26" HEM., S. 25° E., 15² FT. WITH A SCRIBE
 MARK "S" SHOWING IN A PARTIAL HEALED FACE.
 FOUND THE S.W. BT LYING ACROSS A RAVINE IN A ROT-
 TED CONDITION.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 AT THE UPHILL SIDE OF THE STONE A REMNANT OF
 THE ORIG. POST IS FOUND EXTENDING 18" INTO THE GR-
 OUND.

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature	Title	Division	Headquarters	Date	7100-52 REV. 65 5
<u>Leonard Whitmore</u>	<u>Forestry tech</u>	<u>Timber</u>	<u>Hebo</u>	<u>9-27-67</u>	

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 I SET A 3" X 3" SPRUCE LIMB MKD. S10 ON W. AND S11 ON E. SIDES.
 I MARK ONE NEW BT. Witnesses: N. Meana
G. Tilton
 30" SPRUCE, N. 46° W., 30 FT. MKD. 1/4 S10 BT.

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
Leonard Whitmore, Tilla. Co. dep. surveyor

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS