OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

I mamook County Surveyor's Office					
SECTION: Located in the TOWNSHIP 1 South RANG			3E 9	West	
NW 1/4 of Section 5					
COUNTY: Tillamook			DATE: 09-30-11		
CORNER DESIGNATION: The Center-West 1/16 corner of Section 5, Township 1 South, Range 9 West, W.M., Tillamook County, Oregon. The			(Please check one)		
			X	Condition Report Only	
intent of this Condition Report is only to perpetuate the position of				Restoration	
the found O.S.B.F. monument and not to validate or certify the position of this Center-West 1/16 corner. The relative position based				Rewitness	
upon the B.L.M. resurvey of the West ¼ of Section 5 in 1963 has not				Unrecorded	
been established; however this monument has been relied upon for				Reset at surface	
timber cuts since 1963.				Referenced Out	
	orations and Surveys, etc.: See su	irvey ma	ps A	-1105, Tillamook County Survey Records.	
Brass cap on a galvanized iron rotten, was found lying on the c Found a 105" diameter x 3' tall diameter Fir tree bearing North	pipe in good condition and stampe ground. rotting Fir stump with no visible scri 33.3' – See Map A-1105). ng North 71° East 21.9' as describe	d as sho ibe mark	wn h	meter Oregon State Board of Forestry ereon. White painted cedar post, partially ated at record position (was an 84" 105, is now gone. The location falls into	
Monument Restoration (Procedures and Description): Set a 12" diameter plastic cylinder and 150 pounds of concrete around found Brass Cap and pipe. Also placed stones around the outside of the plastic cylinder.			Sketch of Set Monument: NOS C W 1/16 C STR 1963 RS401		
	ooth found orange carsonite posts a				
also set a nail and aluminum w **27" diameter Hemlock tree so washer stamped "TC SURV" se ** Indicates yellow metal location	asher stamped "TILL.CO. SURVEY cribed "CW 1/16 S5 BT" which bears et between the scribed 'B & T'. on tag set.	OR" beto South	ween	ich bears North 71° West 19.0 feet. We the scribed 'B & T'. ast 2.5 feet. We also set a nail and brass	
West of an existing logging roa	corner is located approximately 20 f d.	eet			
Firm / Agency Address: TILLAMOOK COUN			S	URVEYOR'S SEAL	
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor and Deputy County Surveyor.				PROFESSIONAL LAND SURVEYOR	
	ess: Danny R. McNutt, PLS 49230, Tillamook County eyor; Michael R. Rice, LSI 16723, Survey Technician		OREGON JANUARY 10, 2006 JOSEPH V. JENSEN		

NOV 3 2011

800K 7

618

60067 RENEWAL DATE: 08-30- 2013