OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT

Tillamook County Surveyor's Office

Section:18, 19, 13 & 24 Township: 1 South Range: 10 & 11 West					
County: Ti	and the second sec	and the second s	Martin Allesia	. Kingang	DATE: 4/16/2025
Corner Designation:					(Please Check One)
Section corner common to sections 18 and 19, Township 1 South, Range 10 West and sections 13 and 24, Township 1S, Range 11 West; Willamette Meridian				ons X	
					Restoration
					Rewitness Not Found
					Reset
					Referenced Out
BLM Field	Note Volume: C	torations, Surveys, etc.: DR-R0331, Page 455 (1887), Haye ness Card #305 (1977), Map A-372	s Bk. E, Pg.1 (1887), Rewitr 6 (1978), Map B-1849 (1994	ness Bk. 1 4), Map B	l, Pg. 96 (1951), Rewitness 3-3831 (2017)
In 1887 (B found 3 of t W.E Ander Surveyor's Brass cap in established Reference N corner due	the 4 bearing trees son set 1/2" iron p Office establishe in a tile filled with two bearing trees Monument. In 20 to erosion of the ewitness card #30	sories: a post was set for the section corners and established 1 new bearing tree bipe and established one new bearin ed a Reference monument to the Sec a concrete stamped "REFERANCE s for the RM. In 2017 (Map B-383 025 (Field Bk. MR 17 Pg. 53-60) th cliff. The Reference Monument and 05) Reference monument to the sec NT S18 S50 44W 51.29 RS 287 197	e. In 1951 (Rewitness Bk. 1, g tree. In 1977 (Rewitness C ction corner. They set a 2" ir MONUMENT S18 S 50 44 1) Stuntzner Surveying adde e Tillamook County Survey d all its bearing trees were for tion corner N50°44E 51.29'	, Pg. 96)(Card #305 ron pipe w W 51.29 ed one new or's Offic bund. See 10" tile w	Rewitness Bk. 4 Pg. 89)) the Tillamook Couty with a 3" Tillamook County RS 287 1977" and w bearing tree to the se did not find the section below for references.
#305: 18" h spruce S42° YMLT) nov	emlock N79°E 4 °E 40.0'with WM w no change. (Re	1.16' with WMLT) (B-3831: 23" d MLT) (B-3831: 34" dia. with YMLT ewitness card #305: 86" hat section Longitude: -123°58'04.54424"	ia. with YMLT) now no char) now no change. (B-3831	nge. (Rev : 24" dia	witness Card #305: 30" dia.
	were tied conve	ntionally using GPS established co			91 grid coordinates in US
Survey feet	. Coordinates are	provided hereon and are given in V	WGS 84 Latitude and Longit	tude.	
Computed S	Southeast corner	S13 T.1S, R.11W: Latitude: 45°28	'42.90058" Longitude: -	-123°58'0)5.10190"
computed c	orner. Accessorie	Wildlife Service 3 ¹ /4" brass cap sta es to fish and wildlife brass cap (B- E 9.07' with YMLT) no change. (E	3831: 27" dia. spruce S3°E	21.36' wi	th YMLT) no change. (B-
Latitude: 45	°28'42.90039	Longitude:-123°58'06.88353"			
Found: (B-	1849) 5/8" rebar	with yellow plastic cap marked "H Longitude: -123°58'01.92926"	ILB INC." \$85°34'50"E 22	6'. Now	\$88°03'04"E 226.21'
VMLT= wł	nite metal locatio	n tag			
	low metal locatio				
Location:	South $\pm 300^{\circ}$ and	West ± 280 ' From the intersection of	of Cape Meares Loop Rd. an	d Hwy 1	31
F illamook Fillamook,		or's office: 1510 3 rd Street Suite C,		Surveyo	
Party Chie	f: Travis Porter,	Survey Technician III		ROFES	SIONAL RVEYOR
		L.S. 86926, Tillamook County Surv Tillamook County Survey Technic	/eyor	IND SU MANA OREC	This.
lotes: Digi	tal images taken	of monument and accessories.			R 11, 2012 2 R. RICE 26
		3		NEWAL	12-31-2026