CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 35, 36, 1 and 2 . T's L and 2 N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 8" Ceder bears N31°E 9 1ks.; now 9" uproot, cast of BT scribes remaining.
 - 8" Cedar bears S18°E 25 lks.; now 11" uproot, badly. burned.
- 6" Cedar bears N52°W 14 1ks.; now just root hole remaining.
- 15" Cedar bears \$30°W 43 lks.; now 23" partially uprooted, badly burnt.

RESTORED

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R6W S36 S35 S1 S2 TlN 1954 RE 2311," 32 inches in ground, and from which a:

6" Fir bears S14°E 38.0 ft.; scribed T1N R6W S1 BT. 6" Fir. bears \$43°W 46.8 ft.; scribed TlN R6W S2 BT. 26" Fir stump bears N15°W 14.5 ft.; scribed T2N R6W S35 BT RE 2311.

7" Fir bears N53°E 153.5 ft.; scribed T2N R6W S36 BT.

Oregon State Board of Forestry metal location poster on 6" Fir BT S43°W.

Oregon State Board of Forestry metal location poster on _white.Cedar post 1230 ft. East on W edge FB road. Set 4"x4"x84" white Cedar post 2 ft. NE of pipe.

Dated December 17, 1954

__ under my direction. Restored by Arnold G. Gibson, Ass't. Engr.

RED PROFESS

Present and witnessed by Richard Morris Lloyd Geraths Claude Weikel Forrest Logan