CHAINS RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY Section corner common to Sections 3, 4, 9, 10, TIN, RIOW, W.M., Tillamook County, Oregon ORIGINAL Post (missing) from which a: 6" Hemlock bears N25E 14 lks.; now 9", scribe S visible, rest rotted 15" Hemlock bears N78W 36 lks.; now 24" stub 3' high, badly rotted. 5" Hemlock bears S44W 33 lks.; (now 14.1 feet distance) scribe S visible, rest rotted away. 24" Hemlock bears S40E 14 lks.; now 37", scribe 0 visible, rest unexposed. Var. 212E RESTORED Set $\frac{11}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TIN RIOW S4 S3 S9 S10 1959 RS401", 34 inches in ground, and from which a: 31" Hemlock bears N69W 20.7 ft.; scribed TlN R10W S4 BT RS401. 41" Hemlock bears N451E 43.8 ft.; scribed TlN RlOW S3 BT. 41" Hemlock bears SlOW 34.4 ft.; scribed TlN RlOW S9 BT. Oregon State Board of Forestry metal location poster on original 24" Hemlock BT. Set 4" x 4" x 52" white painted Cedar post 1.0 ft. N.E. of pipe. Dated August 4, 1959 Restored by _ under my direction. Harold Russell, Eng. Tech. I REGISTERED OREGON AND SURVEYO Richard A. Mosris R. Cop Present and witnessed by 401 E. Nylund D. Jones

Book I