

CHAINS

RESTORED CORNERS FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 10 and 15,
T2S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, found 1" x 24" iron pipe out of place) from which a:

- 12" Hemlock bears S54E 9 lks.; now 34", scribes 1/4 S B visible.
- 8" Hemlock bears S70W 9 lks.; now missing.

RESTORED

Var. 21 1/2 E

Set above 1" x 24" iron pipe in place 18 inches in ground, and from which a:

- 16" Hemlock bears N59 1/2 W 13.3 ft.; scribed 1/4 S10 BT RS401.

Oregon State Board of Forestry metal location poster on 16" Hemlock BT.

Set 4" x 4" x 52" white painted Cedar post 1.0' S.E. of pipe.

One Quarter corner common to Sections 14 and 15,
T2S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

6" Hemlock (now missing) from which a:

- 24" Hemlock bears N50E 12 lks.; now just rotted roots remaining.
- 10" Hemlock bears S40W 30 lks.; now 15" badly rotted stump, scribes BT visible, rest of face rotted away.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S15 S14 1960 RS401", 34 inches in ground, and from which a:

- 10" Hemlock bears S28W 26.4 ft.; scribed 1/4 S15 BT.
- 12" Hemlock bears S82E 19.4 ft.; scribed 1/4 S14 BT RS401.

Oregon State Board of Forestry metal location poster on 12" Hemlock BT.


Set 4" x 4" x 52" white painted Cedar post 1.2' S.W. of pipe.

Dated August 19, 1960

Restored by Harold J. Russell under my direction.
H. Russell, Transitman



Richard A. Morris



Present and witnessed by G. Nylund
J. Sehorn

11-5-2010

Found Yellow Metal Oregon Department of Forestry location tag on a very rotten Hemlock stump, now uprooted and appears to be out of position (was a 16" Hemlock N59 1/2 W 13.3')

A picture was taken of the yellow metal location tag.
Joseph V. Jensen P.L.S. 60067
Tillamook County Deputy Surveyor

409