

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 8, 9, 16 and 17, T. 2 S., R. 7 W., W. M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

- 12" Hemlock bears S72 $\frac{1}{2}$ W 36 lks; now missing.
- 30" Hemlock bears N55W 21 lks; now 35" snag, face burnt out.
- 12" Hemlock bears N20E 41 lks; now down 12" stub out of place and badly burnt.
- 20" Hemlock bears S80E 29 lks; now down 20" stub shoved out of place by logging, scribe marks T2S R7W S exposed.

RESTORED CORNER AND BEARING TREES

Set a 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W S8 S9 S17 S16 1951 2311", 2 $\frac{1}{2}$ ft. in ground. Raised mound of stone around pipe from which a:

- 60" Fir stump bears S19W 6.9 ft; scribed T2S R7W S17 2311 BT.
- 38" Hemlock snag bears N20E 39.0 ft; scribed T2S R7W S9 BT.
- 60" Fir stump bears S33E 42.0 ft; scribed T2S R7W S16 BT.
- 60" Fir stump bears N22 $\frac{1}{2}$ W 39.8 ft; scribed T2S R7W S8 BT.

Placed an Oregon State Board of Forestry metal location poster on 35" Hemlock snag BT and marked it: Sec 8 T2S R7W Sec Cor 14 ft. S55E.


Dated December 31, 1951.

This corner was restored by

Arnold G. Gibson

Arnold G. Gibson Assistant Engineer

under my direction.



Present and witnessed by

Don D. Davis

Don D. Davis Assistant Forest Engineer