

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 3 and 34, T2 and 3S  
R7W, WM., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

26" Hemlock bears N34°30'E 35 lks; now 30" snag  
N31°W, scribe marks 1/4 S BT exposed.

13" Hemlock bears N56°30'W 48 lks, now 17" stub 7" high  
N59W, face burnt out.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S34 S3 1952 2311," 2 1/8"  
in ground, from which a:


40" Fir snag bears N43E 22.9°; scribed 1/4 S34 BT  
RE 2311.

40" Fir snag bears S83°E 58.3°; scribed 1/4 S3  
BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster  
on 40" Fir snag BT and marked it: Sec 34 T2S R7W 1/4 Cor 22.9  
Ft. S43W.

Dated August 15, 1952.

This corner was restored by Don D. Davis, under  
my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris  
Richard A. Morris Compassman

Present and witnessed by Robert A. Young  
Robert A. Young Chainman