

CHAINS  
FEET

ADJUSTMENT OF TEMPORARY STAKES TO TRUE LINE POSITION BY SINGLE PROPORTIONATE MEASUREMENT AND ESTABLISHMENT OF MONUMENTS.

Relative to the compass bearing of the random line the true line bears N 89° 22' E a distance of 10369.6 ft.

2562.2

Point for the 1/4 corner to Secs. 6 & 31.  
Adjustment from temp. stake N 28.4 ft. W 37.1 ft.

Set an iron pipe 1½ inches in diam. 3 ft. long, filled with charcoal, with an Oregon State Board of Forestry bronze cap, stamped T2N R5W 1/4 S31 S6 1949, 199.

from which:

A fir 20 inches in diam. bears N 18° W  
a distance of 17.0 ft. scribed T2N S31 1/4 BT 199

A fir 17 inches in diam. bears S 18° E  
a distance of 36.0 ft., scribed TLN 1/4 S6 199

3976.6

Set a 4" x 4" cedar post at the side of road on true line with a metal location poster marked Sec. 31-6 T2N R5W Sec. cor. 1188.0 ft. East.

5164.6

Point for the corner to Sections 5, 6, 31 & 32.  
Adjustment from temp. stake N 57.2 ft. W 74.7 ft.

Set an iron pipe 1½ inches in diam. 3 ft. long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped T2N R5W S31 S32 S6 S5 TLN 1949 199

from which:

A fir 16 inches in diam. bears S 80° E  
a distance of 83.5 ft. scribed TLN S5 199

A fir 4 inches in diam. bears N 18° 30' W  
a distance of 15.6 ft. scribed S31

A fir 12 inches in diam. bears N 45° E  
a distance of 62.4 ft. scribed T2N S32 199

A fir 10 inches in diam. bears S 52° W  
a distance of 64.3 ft. scribed R5W S6 199

Continuing N 89° 22' E on same line between Secs. 5 & 32.  
Beginning new measurement.

2602.5

Point for 1/4 corner to Secs. 5 & 32.  
Adjustment from temp. stake N 86.0 ft. W 112.4 ft.

Set an iron pipe 1½ inches in diam. 3 ft. long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped 1/4 S32 S5 1949 199

(Continued on page \_\_\_\_\_)