

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 29 and 30, T. 1 S., R. 7 W.,
W.M., Tillamook County, Oregon

ORIGINAL

Post; now missing, from which a:

40" Hemlock bears East 35 lks; now 40" down stub roots
in place; scribe marks 1/4 BT exposed.

24" Hemlock bears S85W 18 lks; now a 24" stump; face
rotted off felled log from this stump.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S30 S29 1952 2311",
2 1/2" in ground, from which a:


48" Fir stump bears S63W 9.3'; scribed 1/4 S30 BT 2311.

66" Fir stump bears S75E 46.0'; scribed 1/4 S29 BT 2311.

Placed an Oregon State Board of Forestry metal location poster
on 48" fir stump BT and marked it: Sec 30 T1S R7W 1/4
Cor 9.3 Ft. N63E.

Dated February 28, 1952.

This corner was restored by Don D. Davis,
Don D. Davis Asst. Forest Engineer
under my direction.



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman