

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 1, 6, 31, and 36, T1 and 2S R6 and 7W, WM., Tillamook and Washington Counties, Oregon.

ORIGINAL

Mound of stone 8 links East of Corner, now still remaining, from which a:

- 4" Vine Maple bears N10°30'E 43 lks; now missing.
- 8" Hemlock bears S73°30'E 43 lks, now 18" down snag out of place, scribe marks S R6W S6 exposed.
- 48" Hemlock bears N73°30'W 82 lks, now 48" down snag, face burnt out.
- 48" Hemlock bears S73°30'W 39 lks, now 50" stub 7' high, scribe marks T2S 7W exposed.

At corner found $\frac{1}{2}$ " iron pipe with 2" bronze cap stamped LHL LBR. CORP. T1S R7W 36, 31, 1, 6, R6W T2S 1949.

REWITNESSED CORNER


Raised mound of stone around corner pipe, from which a:

- 66" Fir stump bears N61E 65.6°; scribed T1S R6W S31 BT.
- 36" Fir stump bears S30E 78.3°; scribed T2S R6W S6 BT.
- 42" Fir stump bears S5W 53.2°; scribed T2S R7W S1 BT RE 2311.
- 30" Fir stub 8' high bears N54W 30.9°; scribed T1S R7W S36 BT.

Placed an Oregon State Board of Forestry metal location poster on 66" Fir stump BT and marked it: Sec 31 T1S R6W 65.6 Ft. S61W.

Dated August 15, 1952.

This corner was restored by Richard A. Morris, under my direction. Compassman



Present and witnessed by Robert A. Young Chairman