

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 9, 10, 15, and 16, Township 2 North, Range 9 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 6" Hemlock bears N46W 31 lks; now missing.
- 13" Hemlock bears N67E 55 lks; now missing.
- 14" Hemlock bears S79E 53 lks; now 27" stump, parts of scribe marks BT exposed on stump and scribe marks T2N R9W S on slab of wood lying alongside.
- 11" Hemlock bears S68W 59 lks; now 11" down root stub, out of place, exposed part of scribe mark.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R9W S9 S10 S16 S15 1952 2311," 2 1/2" in ground. Raised mound of stone around corner pipe, from which a:

- 55" Fir stump bears S25E 12.2'; scribed T2N R9W S15 BT.
- 51" Fir stump bears S56°30'W 43.7'; scribed T2N R9W S16 BT.
- 54" Fir stump bears N4°30'E 68.0'; scribed T2N R9W S10 BT RE 2311.
- 48" Fir stump bears N49W 30.5'; scribed T2N R9W S9 BT.

Placed an Oregon State Board of Forestry metal location poster on 55" Fir stump BT and marked it: Sec 15 T2N R9W Sec Cor 12.2 Ft. N22°W.

Dated June 7, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman