

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 14 and 23,
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

36" Hemlock bears S10E 14 lks.; now just rotten roots remaining in place.

5" Hemlock bears N70E 24 lks.; now 14" uproot, roots and root hole in
place, edges of rotted out face visible with grown over axe work.

NOTE: This corner point agrees exactly with W.E. Anderson survey for
Fred Wyss in March 1935.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S14 S23 1959 RS401", 33 inches in ground, and from
which a:

21" Hemlock bears N36E 37.5 ft.; scribed 1/4 S14 BT RS401.

16" Hemlock bears S45W 32.0 ft.; scribed 1/4 S23 BT.

Oregon State Board of Forestry metal location poster on 21" Hemlock BT.
Set 4" x 4" x 60" white painted Cedar post 1.0' S.E. of pipe.

Dated December 31, 1959

Restored by



Richard A. Morris

MAY 10, 1957

Richard A. Morris

401

Present and witnessed by H. Russell
R. Cop
E. Nylund