

Route 2, Box 261

Dallas, Oregon.

October 2, 1961.

County Surveyor

Tillamook County

Dear Sir:

On Sept. 16, 1961, I re-established the South  
1/16 corner between Sections 33 & 34, Township 2  
South, Range 8 West, Willamette Meridian.

One bearing tree and the monument being des-  
troyed by logging, I reset the monument with a  
1" x 40" iron pipe and a mound of stone around the  
pipe. One original B.T., an 8" Hemlock stump, bears  
S.54 $\frac{1}{2}$  E. 59 lks. marked ( S 1/16 S 34 BT ) and  
I scribed a 58" Douglas Fir stump, S 67 $\frac{1}{2}$  W., 124 lks.  
marked ( S 1/16 S 33 BT ).



Sincerely,

Harry Miller, R.S. #400

Witness:

Leonard Zygar Leonard Zygar

J. L. Gould Pat Gould



535