

(111)

N 76 1/5 2510

4-76

Found 2" Iron Pipe Flush with
The Ground. ~~with~~ witnesses

Found 2 Old Bearing Trees &
One New Bearing Trees, All
Trees Have Visible Scribings.

- 12" Pine S52W 9⁵¹ (1/4 BT CS) (old)
- 12" Pine N114W 14¹⁷ (" " " ") (old)
- 10 Pine N07E 23⁸¹ (" " " ") (New)

I Set A 4x4x48 white Old Post 19 Southly
of Cor.

G Another

SA Skimmer 4-6-66

Field viewed, checked, #118/66
Record " " off Kamin - CS

BOOK 30

CHAINS

25 2510	2510	3-4-8	
25 2510	2510	3-4-8	
Found 2 1/2 Iron Bearing Trees 24" Spk N25°E 13 ²⁰	Pipe ± 6 Above Trees which Scribings vs " Not vs " vs.		
16" Spk N79°E 18 ⁷⁹			
26" Spk S31°E 28 ⁸²			
I Set 4x4x48 white 1" South of Cor.	Code Post		
No New Bearing Trees	Need		
SA Skimmer 9/27/65			4-50
G Another			
Field checked record checked #118/66 off Kamin - CS.			

BOOK 30

L. L. DANLINO CORP.
TACOMA, WASH., U.S.A.

WATERPROOF

No. 312