

TOWNSHIP PLAT NO. 279

For Sale by Kilham Stationery & Printing Co., Portland, Oregon

Township No. 1 North Range 9 West E. W. M.  
Tillamook County, Oregon

	6	5	4	3	2	1
	7	8	9	10	11	12
1	3	3 3				
2						
2	18	17	16	15	14	13
2						
1						
	19	20	21	22	23	24
	30	29	28	27	26	25
	31	32	33	34	35	36

1. N. 9.

21	20	19	18	17	16	15
22	21	20	19	18	17	16
23	22	21	20	19	18	17
24	23	22	21	20	19	18
25	24	23	22	21	20	19
26	25	24	23	22	21	20
27	26	25	24	23	22	21
28	27	26	25	24	23	22
29	28	27	26	25	24	23
30	29	28	27	26	25	24

Section corner 24 19 T. 1 N. R. 9 and 10 W. We found an old iron pipe at this section corner, and 2 hemlock B.T.'s. We drove another pipe and set a 4" x 4" cedar post, and scribed an 18" hemlock S 19° E 46.0' S 20 B.T. The following original B.T.'s are present:

A 16" hemlock S 42° W 11.2' S 19 B.T. Yellow tag  
An 18" " N 55° W 28.0' S 18 B.T.  
A 30" " N 26° E 6.0' S 17 B.T. Yellow tag

Scribed by O. R. Miller  
Witnessed by E. Erickson, Wm. Jordan,  
O. B. Jackford, July 26, 1950

Section corner 12 7 Township 1 North, Ranges 9 and 10 W. We drove an iron pipe for the corner to these sections and scribed the following trees:

A 32" hemlock S 66° E 11.8' S 18 B.T. Yellow tag.  
A 16" cedar N 43° E 40.7' S 7 B.T.  
A 4" hemlock S 65° W 29.7' S 13 B.T.

Scribed by O. R. Miller, July 31, 1950  
Witnessed by E. Erickson, O. B. Jackford,  
W. E. Jordan, 1950

Var. 20° 45' E.

1 

1

Swanwick 1 North Range 9 West

1. Section corner 11 18 T. 1 N., R. 9 and 10 West. After running all north, south  
21 19 11 18

east and west lines from sec. corner 21 19 T. 1 North, R's. 9 & 10 West, I made a very diligent search for this section corner or evidence of the same and find a 20" hemlock stub badly decayed. No visible staves. Not entirely convinced that this is the original bearing tree for this section corner, I begin at Section corner 11 18 T. 1 S R's. 9 and 10 W and run north, retracing the range line to 11 18 verify the evidence at Section cor. 21 19 T. 1 N., R's. 9 and 10 W. Checking with the original field notes in retracing the range line I find the creek and ridge lines in accord with those described in the original field notes. Proceeding north to the approximate position of the section corner I find the hemlock stub to be on the original range line. The position of this evidence is further verified by the stream line to Moss Creek approximately 100 feet north of the position of the corner.

I am firmly convinced that this hemlock stub is the remains of the original bearing tree marked by the original land surveyors in 1873. I am certain beyond any doubt that restoring this corner from this evidence will place this corner in the original position and that a restoration of this corner by any other method would result in this corner being erroneously set. From this bearing tree I set a 3" x 3" x 30" cedar post for the corner as per distances bearing as recorded in the original field notes. This corner was referenced as follows:

8" hemlock S 3° E 9.3 feet      Lead number S 17  
30" spruce N 27° E 50.8 "      "      "      S 18  
32" spruce N 34° W 72.2 "      "      "      S 15

Referenced and restored by:  
C. R. Miller of L'Co.  
Witness: J. Rodgers  
D. B. Jackson

Swanwick 21, 1911

2. Section corner 18 17 T. 1 N R 9 W. We found an old iron pipe at this section  
19 20

corner, and 3 hemlock B.T's. We drove another pipe and set a 4" x 4" cedar post, and scribed an 18" hemlock S 19° E 44.0' S 20 S.E. The following original B.T's. are present:

A 16" hemlock S 42° W 11.8' S 19 N.E. Yellow tag  
An 18" "      N 55° W 28.0' S 18 S.E.  
A 20" "      N 26° E 6.0' S 17 S.E. Yellow tag

Scribed by C. R. Miller  
Witnessed by H. Erickson, Wm. Jordan  
D. B. Jackson, July 24, 1910

3. Section corner 12 7 Township 1 North, Ranges 9 and 10 W. We drove an iron pipe  
13 14

for the corner to these sections and scribed the following trees:

A 34" hemlock S 66° E 11.8' S 18 S.E. Yellow tag.  
A 16" cedar      N 43° E 40.7' S 7 S.E.  
A 4" hemlock S 65° W 19.7' S 15 S.E.

Scribed by C. R. Miller, July 31, 1910  
Witnessed by H. Erickson, W. B. Jackson  
W. B. Jackson

Sec. 21 19

1  
A of

Section 1. North. June 9, 1922

1. Sec. corner  $\frac{11}{12}$  T. 1 N., R. 9 and 10 W. After running all north, south, east and west lines from Sec. cor.  $\frac{11}{12}$  T. 1 N., R. 9 and 10 W., I made a very diligent search for this Section corner or evidence of the same and find a 10" hemlock stub badly damaged. In writing above. Not entirely convinced that this is the original bearing tree for this section corner, I set a at Sec. corner  $\frac{11}{12}$  T. 1 N. R. 9 and 10 W and ran north, retracing the range line

to verify the evidence at Section corner  $\frac{11}{12}$  T. 1 N., R. 9 and 10 W. Starting with the original field notes in retracing the range line I find the creek and ridge line in accord with those described in the original field notes. Proceeding north to the approximate position of the section corner I find the hemlock stub to be on the original range line. The position of this evidence is further verified by the stream tie to Moss Creek approximately 100 feet north of the position of the corner.

I am firmly convinced that this hemlock stub is the remains of the original bearing tree marked by the original land surveyors in 1873. I am certain beyond any doubt that restoring this corner from this evidence will place this corner in the original position and that a restoration of this corner by any other method would result in this corner being erroneously set. From this bearing tree I set a 3" x 3" x 36" cedar post for the corner as per distance and bearing as recorded in the original field notes. This corner was reformed as follows:

8" hemlock S	3" E	9.3 feet	Lead number	S 10
10" spruce	S 27° E	30.8 "	"	S 10
12" spruce	S 34° E	72.2 "	"	S 13

Referenced and restored by:

G. E. Miller of L.S.O.

Witnesses: J. Rodgers

G. E. Johnson

June 11, 1922

2. Sec. corner  $\frac{11}{12}$  T. 1 N. R. 9 W. We found an old iron pipe at this section cor., and 3 hemlock S.T's. We drove another pipe and set a 4" x 4" cedar post and marked an 10" hemlock S 17° E 45.0' S 30 S.T. The following original S.T's. are present. See below.

Settled by G. E. Miller

Witnessed by E. Erickson, Wm. Jordan,

G. E. Johnson, July 26, 1922

Original S.T's. found for sec. cor.  $\frac{11}{12}$  T. 1 N. R. 9 W.

A 10" hemlock	bears S 41° W	11.7'	S. 19 S.T.	Yellow tag
An 10" "	" S 35° W	30.2	S. 10 S.T.	
A 10" "	" S 30° W	6.0	S. 17 S.T.	Yellow tag



Section 7, North, June 3, 1914

1. Section corner  $\frac{13}{15}$  7. 1 X 2 1/2, 9 and 10 W. We drove an iron pipe for the section corner and scribed the following trees:

- A 10" hemlock 8 60° E 11.5' 8 16 N.W. Yellow tag
- A 10" cedar 8 45° E 40.7' 8 7 N.W.
- A 4" hemlock 8 65° W 29.7' 8 13 N.W.

Scribed by C. E. Miller

Witnessed by M. Erickson, C. H. Jackson

Map. 10° 41' N.

W. H. Jackson, 10/10/14



Tranche 1 North, Area 1 West.

1. We found an old iron pipe at Sec. Cor.  $\frac{14}{19}$  -  $\frac{14}{25}$  T. 1 N R + W. and 1 wooden S.T'n.

We drove another pipe and set a 4" x 4" cedar post and verified an 18" wooden S.T'n 19' N 14.0' S 20 S.T. The following original S.T'n. are present:

A 16" wooden S	42" N	11.0'	S 19 S.T.	Yellow tag
An 18" "	N 31" W	20.0'	S 18 S.T.	
A 30" "	N 26" N	6.0'	S 17 S.T.	Yellow tag

Verified by C. R. Miller

Witnessed by H. Erickson, Wm. Jordan

C. R. Jackson, July 25, 1960



## Traverse 1 North, Range 9 West

1. Section corner  $\frac{16}{17}$  N. 1 W 2 9 W. We found an old iron pipe at this section corner and 3 handout N.T.'s. We drove another pipe and set a 4" x 4" cedar post, and drilled on 15" handout S 19" E 45.0' S 20 N.T. The following original N.T.'s. are present:

A 15" handout S 45° E	11.0'	S 19 N.T.	Yellow tag
An 15" "	S 55° E	25.0	S 18 N.T.
A 15" "	S 35° E	0.0	S 17 N.T. Yellow tag

Recorded by: C. R. Miller  
 Witnessed by H. Erickson, Wm. Jordan,  
 C. R. Johnson, July 26, 1940

