

CHAINS

Page # 2

36" Fir N68°30' W 72 links
 now badly rotted 42" stump
 20" Fir S45°45' W 19 links
 now 28" stump "9WS12" visible
 24" Fir S45°E 35 links (missing)

RESTORED:

Set 5/8" x 30" iron pin 26" in ground, 1.05 feet East of Pipe
 Set 4" x 4" x 48" white post 0.6 feet South of pin
 16" Alder N64°W 69.1 feet, scribed "T6SR9WS1CCBT"
 22" Fir S54°30'W 64.4 feet, scribed "T6SR9WS12CCBT"
 Yellow Corner tag on 22" Fir BT

1/4 CORNER EAST SIDE SECTION 12

ORIGINAL:

Post (missing)
 14" Fir S20°E 19 links (missing)
 16" Fir S10°W 26 links (missing)
 Re-Established: set 5/8" x 30" iron pin 25" in ground
 set 4" x 4" x 48" white post 1 foot South of pin
 20" Fir S15°30' W 161.9 feet scribed "1/4S12BTRS691"
 5" Alder N15°30'W 73.1 feet scribed "1/4 S12BT"
 Yellow corner tag on 20" Fir BT

SECTION CORNER 7 and 18 T6SR8W

ORIGINAL:

Post (Missing)
 18" Fir N60°30'E 87.1 feet (missing)
 24" Fir S83°E 47.5 feet
 now 28" stump "IRBT" visible
 18" Fir S44°W 15.2 feet
 now 30" stump "BT" visible
 RESTORED: set 5/8" x 30" iron pin 26" in ground
 set 4" x 4" x 48" white post
 18" Hemlock N70°45'E 107.8 feet scribed "T6SR8WS7BT"
 24" Spruce S11°45'E 98.8 feet scribed "T6SR8WS18BTRS691"
 Yellow corner tag on 10" Fir S47°W 43.8 feet (closing corner BT)
 24" Fir stump bears North 130.5 feet with old line notches visible

CLOSING CORNER 12 and 13

ORIGINAL:

Post (Missing)
 30" Fir N50°W 10 links (missing)
 28" Fir S20°W 48 links
 now 30" stump "BT" visible
 24" Fir S60°E 85 links
 now 28" stump "IRBT" visible
 RESTORED: set 5/8" x 30" iron pin 26" in ground
 set 4" x 4" x 48" white post 1 foot South of pin
 10" Fir S33°45'W 57.9 feet, scribed "T6SR9WS13BTRS691"
 14" Fir N82°W 113.5 feet, scribed "T6SR9WS12BT"
 Yellow corner tab on 10" Fir BT

1/4 CORNER 12 and 13

ORIGINAL:

BOOK 3

BOOK 3