

CHAINS

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

T.3.S.R.8.W.

(refer to 5450)

27 | 26 Car. to Secs. 26-27-34-35
 34 | 35 Original Monument
 4"x4" past 4 feet long

Original Witnesses:

72" fir, N.26°30'W., 33 LKS. Mkd. T.3S.R.8W.S.27B.T.
 22" fir, S.29°W., 64 LKS. Mkd. T.3S.R.8W.S.34B.T.
 34" fir, S.45°E., 88 LKS. Mkd. T.3S.R.8W.S.35B.T.
 28" fir, N.67°30'E., 82 LKS. Mkd. T.3S.R.8W.S.26B.T.

I found the original post is gone. Found a rotted snag, S.29°W., 64 Lks. with most of its outer shell fallen upon the ground. Two pieces lying at the base show the edges of the witness blaze with the marks rotted away.

The N.W. and S.E. BTs are in their proper bearing and distances but all marks are rotted away. The N.E. BT is in its proper bearing but the distance is 52 Lks. not 82 Lks. as recorded in the original notes of which may be a typing error. I found a blazed line snag, as recorded in original notes, the proper distance due west of this corner point. Also an original side blaze is on a 38" green fir 26 feet south of this corner point.

I am convinced by these evidences that this is the original corner point located in a shallow draw running east. I set a 3"x3" vinemaple squared post 48" above ground. I marked four new BTs:

18" fir, S.10°E., 80Lks. Mkd. T.3S.R.8W.S.35BT
 38" fir, S.13°W., 39Lks. Mkd. T.3S.R.8W.S.34BT
 15" fir, N.16°W., 53Lks. Mkd. T.3SR.8W.S.27BT
 18" alder, N.18°E., 48Lks. Mkd. T.3S.R.8W.S.26BT

BOOK 3

BOOK 3