

CHAINS

Page 3. cont. T.3S.R.10W.

I found $3/4$ " galv. pipe 18" above the ground. Along side is a 3×4 " post 10" above the ground Mkd. $1/4$ S. on south and $1/4$ S. on North sides. It is not the original post.

I found a rotted hemlock stump, S.5°W., 17Lks. with marks rotted away. A yellow tin is on the stump marked; "Do Not Destroy."

The N.E. BT is in its proper bearing and distance but all marks are rotted away.

I marked 2 new BTs:

FIR AED 10-67
 5" pine, S.69°30'E., 19Lks. Mkd. $1/4$ S.17BT
 4" fir, N.59°30'E., 26 Lks. Mkd. X BT

witnesses: Wayne Abbey
 Bill Heitsman
 by Leonard Whitmore
 Tillamook Co. Deputy Surveyor
 4-11-63

8 $1/4$
 9

$1/4$ Corner between secs. 8-9
 Original Monument 4×4 " post
 Original Witnesses:

14" hemlock, S.40°W., 15 Lks. Mkd. $1/4$ S BT
 18" fir, N.54°E., 12 Lks. Mkd. $1/4$ S BT

I found 3" x 3" squared fir limb 24" above ground. Not the original post.

Found a fallen 16" hemlock, S.40°W., 15 Lks with scribe marks showing but not legible.

Found a location poster on a 16" fir, N.80°W., 11 $1/2$ ft. by M. Whitmore 9-1-59. This corner was found then by compass and chain.

I marked two new BTs:

50" snag, S.40°E., 35 Lks Mkd. $1/4$ S9 BT
 16" dead fir, N.81°30'W., 18 Lks. Mkd. $1/4$ S8 BT

witnesses: Wayne Abbey
 Bill Heitsman
 by Leonard Whitmore
 Tillamook Co. Deputy Surveyor
 4-12-63

BOOK 3

BOOK 3