

CHAINS

RESTORED CORNER FOR W. A. MARKHAM

NOTICE OF RE-WITNESS TO  
 $\frac{1}{4}$  CORNER OF SECTIONS 1/6, T 2 N, R 10/9 W

ORIGINAL

Original Corner was a Post with:

Vine Maple	5" N18°E	12 links
Cheery	3" S11°W	13 links

In 1947 I found the Vine Maple BT, dead and down, cut face plain, but marks rotted away, and measuring properly therefrom, a fence corner which was taken to be the property corner on the line between Sec. 1 and the NW $\frac{1}{4}$  and SW $\frac{1}{4}$  of Sec. 6.

I was told by Harry McCuen, a long time local resident, that this maple was definitely the BT as he remembered when it was alive and showed the iron marks. Accordingly, I placed a 3/4" Galv. Pipe against the fence corner post and a yellow aluminum location poster on the post. Since then, the farm owner has cleaned out his fence rows and disposed of the remains of the dead maple BT. On Dec. 9/57 I made a new BT:

RESTORED

ALDER, 8", N 07°W 32.5 feet, scribed on bark  
 $\frac{1}{4}$  S 1 BT 1842"

Restored by

