

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

(39)  $\frac{1}{4}$   $\frac{34}{35}$  1510

Found 2" Iron pipe Badly  
Rusted & Two Bearing Trees  
36' Hem S10°30'W 69<sup>5</sup>

Now 40" Hem This Tree is on  
South Side of Hwy 131  
20' Hem N81°15'W 88<sup>10</sup>

Now 24' Hem this Tree is on North  
Side of Hwy 131  
Cor is on Top of North Cut  
Bank ± 5 North of Top of Cut

I set A New 1" Iron Pipe inside  
of old pipe & set A 4x4x48"  
white ced post ± 1' West of  
Cor No New Bearing Trees  
Needed

SA Skinner 10/11/65  
G. Arthur

	See Book	Page
BOOK 5	" "	4-67
	" "	4-33

10/27/70 *Went* CS