

County Surveyor's Record, Tillamook County, Oregon

CHAINS

(185)

Int Pt of Warner Add Idaville
 Sec 1-2 ~~1510~~ 1510

Found. A $\frac{3}{4}$ " AXEL \pm 20" Deep
 AXEL is in Bad Shape so I Replaced
 I set A 3" Iron Pipe 30" Long
 24" Below The Surface.

Cor Falls \pm 0' Southly of
 A 16" Conn. Culi. Running Ely E
 Wly \pm 2 Wly \pm 1 Sdy of End
 of Culi. Also A Ditch Line
 Running South of Cor By \pm 2.

New B.O.'s
 SW Cor Idaville - Bible Church
 148⁶²

PP # BC-A-2-R25-R1
 50⁶⁵

NW Cor Gas Pump Pad
~~80⁴³~~ 80⁴³

Shell O.I. Sign 4" Iron Pole ϕ
 6⁵⁴

SA Skinner
 A E Duncan 4-27-67

12/16/70
 J. L. Carter C.S.

BOOK 5