

County Surveyor's Record, Tillamook County, Oregon

CHAINS

③

1/2 Cor 97 5510

Did Not Find old 1/2 Cor Stone
 Believed To Be destroyed By Cat
 Work So, I set A 1 1/2" Iron Pipe
 For Cor ± 2" Above Ground
 See Page 2 for Setting of Cor.
 \$ New Bearing Trees

24' Spr	S53°W	71 ⁰⁴ '	^{sensed} 1/2 S7BTC5
24' Spr	N64°30'W	58 ³⁹ '	1/2 S6BTC5

SASKimmer 10-20-65
 G. Arthur
 (See Rewrites Books)
 (This Cor is set From Bearing &
 Distance From Map B-391)

BOOK 5 5506

29/30
 ← 4 | 3 5507

BOOK 5 1