CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

DIAGRAM

T 5 S R 9 W SE 1/16

Sec. 5

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

At proportionate measurement, I set a 2 1/2" x 30" galvanized iron pipe with a brasscap riveted to the top marked:

R 9 W

SE 1/16 S 5

1975

RPLS 942

from which:

15" Fir N 70° E 5.9 feet mkd. "SE 1/16 S 5 BT

21" Fir S 15° W 13.0 feet mkd. "SE 1/16 S 5 BT"

All bearing trees have been banded with red paint and attention signs and BT tags have been attached. All scribes have a 3/4" brass washer, with "LS 942 engraved on it, nailed in the face.

Witnessed: E. W. Tatro

...... County of for record on the day of

(COUNTY OFFICIAL) by (DEPUTY)

Morte a. Cook

Set this 31st day of January 1975

317

Monte A. Cook

Forest Technician



TIMBERLAND SERVICES, INC. 1010 Airport Road P. O. Box 668 Albany, Oregon 97321 Telephone (503) 926-9404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING

☆ GPO 796-333

REGISTERED

PROFESSIONAL

AND SURVEYOR

WIGHTMAN II

BOOK 5 1

Form R6-7100-57 (9/71)