CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was originally set by the G.L.O. in 1880 under contract No. 364. They set a 12"x6"x6" stone with no bearing trees.

DIA	SF	\A.			
Т	5	S	I	? 5	9 W
	S	5	S	4	
sma-yead	S	8	S	9	Associal .

Description of corner evidence found:

I found no evidence of the original corner. In 1895 the County Surveyor set a 12"x10"x5" stone and marked an 80" Fir snag N 80° W 12 links. I found a 15"x9"x3" stone in a stone mound at the called bearing and distance from an 80" snag. I can find no record of the method of remonumentation.

Description of monument and accessories I established to perpetuate the original location of this corner

After consultation with the G.L.O., I disclaim this stone as a valid corner. At proportionate measurement, I set a 2 1/2" x 30" galvanized iron pipe with a brasscap riveted to the top marked:

from which:

40" Fir S 47° W 37.4 feet mkd. "T 5 S R 9 W S 8 BT"

34" Fir S 64° E 23.5 feet

44" Hemlock N 89° W 59.1 feet mkd. "T 5 S R 9 W S 5 BT"

37" Fir N 28° E 55.5 feet mkd. "T 5 S R 9 W S 4 BT"

15"x9"x3" Stone (1895) N 25° 03' 54" E. 200.68 feet

All bearing trees have been banded with red paint and attention signs and BT tags have been attached. All scribes have a 3/4" brass washer, with "LS 942 engraved on it, mailed in the face.

Witnessed: E. W. Tatro
E. W. Lamb

(COUNTY OFFICIAL) by (DEPUTY)

Set this 30th day of January 1975

Monte a. Cook

Monte A Cook Forest Technician 319

TIMBERLAND SERVICES, INC. 1010 Airport Road P. O. Box 668 Albany, Oregon 97321 Telephone (503) 926-9404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING CAND SURVEYOR

CANTON M. WIGHTMAN II

REGISTERED PROFESSIONAL

☆ GPO 796-333

ECOK 5

Form R6-7100-57 (9/71)