

County Surveyor's Record, Tillamook County, Oregon

CHAINS

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 3, 4, 9 and 10, T1N, R5W, W.M., Washington County, Oregon.

ORIGINAL

18" yew for corner (now an 18" uproot, found 1 1/2" Galv. iron pipe in the center of the uproot hole-see below) from which a:

- 3" Yew bears S25°E 17 lks.; missing.
- 12" Hemlock bears S65°W 22 lks.; now 18" snag with face visible, scribes rotted away.
- 12" Hemlock bears N50°W 47 lks.; missing.
- 6" Hemlock bears N34°E 35 lks.; missing.
- 3 lk. stream bears North 1.5 chains, course west; now 112 feet.
- 2 lk. stream bears East 3.5 chains, course NW; now 241.0 ft. crs. N20W from S20E.

RESTORATION by City of Forest Grove Engineers, 1959.

1 1/2" GIP with a 3/4" IP inside, with a brass tag wired on it stamped PE 1508 (in place).

Var 21 1/2°E

REWITNESSED

From above 1 1/2" Galv. iron pipe a:


- 6" Fir bears S75 1/2°E 6.0 ft. to face; scribed T1N R5W S10 BT.
- 10" Fir bears S49 3/4°W 21.2 ft. to face; scribed T1N R5W S9 BT RS707.
- 7" Fir bears N82°W 6.5 ft. to face; scribed T1N R5W S4 BT.
- 7" Fir bears N81°E 7.8 ft. to face; scribed T1N R5W S3 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SW of corner pipe. Oregon State Forestry Department metal location poster on 6" BT.

Dated July 9, 1975.

Rewitnessed by Loren Steele under my direction.
Loren Steele, Forest Engineer

Present and Witnessed by P. Brunson
J. Martinez



Washington County Surveyor
RECEIVED
SEP 16 1975
HILLSBORO, OREGON

BOOK 5