

County Surveyors Record, Tillamook County, Oregon

SURVEY FOR  
LONGVIEW FIBRE COMPANY AND  
OREGON-WASHINGTON PLYWOOD COMPANY

CHAINS

SE $\frac{1}{4}$  SECTION 3, T6S, R10W

BY LONGVIEW FIBRE COMPANY AND  
OREGON-WASHINGTON PLYWOOD CO.

November 3, 1970  
Plat #546-B

Section 3 was initially partially subdivided in 1967 by Longview Fibre Company. This survey is an extension of the 1967 work to further subdivide (the SE $\frac{1}{4}$ ) the said Section 3. Bearings given are tied to the previous survey.

This survey was initiated at the 1/4 corner common to sections 3 and 2, using a Theodolite T-1AE and 300-foot tape. Found 1 $\frac{1}{2}$ " iron pipe, with original bearing tree and 1 rescribe as recorded by Longview Fibre Company in 1967.

T6S R10W

		1/4	
FEET		3	2

thence S 4° 30' W between sections 3 and 2

1321.3 Found a 1" galvanized iron pipe, established by proportionate measurement by U.S.F.S. in 1952. Found 2 bearing trees with faces grown over. I drove a 1 $\frac{1}{4}$ " x 36" stainless steel pipe over the 1" pipe.

		S 1/16	
	S3		S2

2540.0 Spring, course west.

2642.6 The section corner. Found 1 $\frac{1}{4}$ " stainless steel pipe in the ground for the corner. Found original bearing trees with scribe visible.

	T6S	R10W
	3	2
	10	11

From which I found:

(continued on next page)

BOOK 5

BOOK 5