

TOWNSHIP 5 SOUTH, RANGE 10 WEST

1/4 Corner, Sections 25/36, T5S, R10W

See LFCo. Map #701

Found 1/4" iron pipe for the corner, established by U.S. Forest Service in 1960, by proportionate measurement.

From which I found the following new bearing trees:

24" Hemlock bears S 2° E 29.0 feet; scribed "1/4 S36 BT".

2

18" Hemlock bears N 61° E 2.0 feet; scribed "1/4 S25 BT".


August, 1972

Found by: Wayne Brewer, LFCo.

Witnesses: R. McCollam, R. Thompson

1/4 Corner, Sections 36/31, T5S, R10W

Found iron pipe for the corner, restored by Bureau of Land Management in 1962, with a brass cap marked as illustrated:



From which I found the following new bearing trees:

12" Hemlock bears N 39° W 16.5 feet

1

36" Fir Bears N 8° W 24.0 feet

2

22" Fir bears S 62° E 24.0 feet

Corner is on steep west slope.

August 16, 1971

Found by: Wayne Brewer, LFCo.

*See map A-2512*