

1150.0 Enter bench

1306.2 Standard W 1/16 Section 36

Established and monumented by Longview Fibre Company with a 1 1/4" x 36" stainless steel pipe.

From which:

18" Hemlock bears N 48° W 14.60 feet; scribed "Std W1/16 S36 BT"; screw nail, lead washer, yellow aluminum section marker plate.

36" Hemlock bears N 42° E 14.95 feet; scribed "#STD W1/16 S36 BT"; screw nail, lead washer, yellow aluminum section marker plate.

2070.0 Road, North-South

2612.4 Standard 1/4 Section 36

Established and monumented by Longview Fibre Company with a 1 1/4" x 36" stainless steel pipe.

From which:

10" Hemlock bears N 17° W 8.05 feet; scribed "1/4 S36 BT"; screw nail, lead washer, yellow aluminum section marker plate.

15" Hemlock bears N 74° E 39.65 feet; scribed "1/4 S36 BT"; screw nail, lead washer, yellow aluminum section marker plate.

2672.0 Same road, bearing S 16° E

3121.0 Same road, bearing N 20° E

3806.0 Spur ridge, North-South


5210.0 Edge high bank of creek

5224.8 T5S R10W | T5S R9W Standard township corner

S36 | S31

T6S

Found iron pipe with U.S. B.L.M. brass cap, marked as illustrated:



From which I found the bearing trees as scribed by U. S. Forest Service in 1958:

18" Alder N 9° E 38.0 feet

42" twin Hemlocks N 28° W 26.5 feet