History of original corner establishment:

Fenton and Maloney survey in 1887 50" fir bears N 46° 45" E 44 1ks. 8" hemlock bears S 50° 30 W 27 1ks.

DIAGRAM

N 1/16 on W line S6 only
T6S, R8W, WM

Description of corner evidence found:

Found 1/2" iron rod Found 50" fir stump bearing N 46° 45' E 29.0' with scribe marks and BT sign Found remains of rotted tree S 50° W 17.8'

1174 ft. South of NW Cor Section 6 and approximately 15 ft. North of 4 ft. log lying East and West

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3" brass cap and 2" iron pipe 6" above ground, stamped:

Set steel fence post with attention sign 3 feet N of mon.

Painted face of blaze red on 50" fir stump

Placed 1/2" iron rod on N side of mon. in hole

An alder 8" in diameter bears S 65° E 12.85' side center scribed "N 1/16 S6" with brass washer and "BT" on lower blaze

A fir 11" in diameter bears N 39° 15' E 26.70' side center scribed "N 1/16 S6" with brass washer and "BT" on lower blaze

Painted face of blazes and 6" band red, placed Bearing Tree and Attention signs on back of both new bearing trees

T6S
| R8W | N 1/16 | S6 | 1975 | PE 1956

Lee My B. 701

Office of SUNTY State of County of County of State of County of Instrument was filed in this office for record on the County Official)

(COUNTY OFFICIAL)

County of The Manager State of County of

Form R6-7100-57 (9/71)

☆ GPO---798-276