CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

There is no record of this corner ever being legally set.

DIAGRAM							
	T	4	S	R	8	W	W.M.
N 1/16							
S 3 S 2							
			L	\bigcirc	· .		

Description of corner evidence found:

None

Description of monument and accessories | established to perpetuate the original location of this corner:

At proportionate measurement I set a 2 1/2" X 30" galvanized iron pipe with a flared bottom and a brasscap riveted to the top marked:

T4S R8W From Which, N 1/16 20" Douglas Fir N 70° W, 7.7 feet mkd "N 1/16 S 3" "B.T." S 3 S 2 1977 16" Douglas Fir N 18° E, 10.4 feet mkd "N 1/16 S 2" "B.T. RLS 1073

I set a 6' steel fence post with a "Broperty Boundary" sign and "Land Survey Monument" sign. All bearing trees have brass washers, attention signs, bearing tree tags, and red painted bands on them.

Witness: Jay McDonald

D. Mike Jackson Engineering Technician

REGISTERED PROFESSIONAL LAND SURVEYOR OREGON
JULY 17: 1970
KENNETH M. WIGHTMAN II
942

Office of County of County

94

Contin by County Sucutional (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

Book 6



TIMBERLAND SERVICES, INC. MDEREAND JETYOLO, 174 1010 Airport Bond P. O. Box 668 Albany, Oregon 97321 Telephone (503) 926-9404

LAND SURVEYING - ENGINEERING LAND USE PLANNING - ROADS FORESTRY CONSULTING

PROFESSION. OREGON EDGAR R. COOK

REGISTERED