

REMARKS

10" hemlock bears N34°E, 30 links, marked "T3N R10W S4BT" (now a 30" stump).
8" hemlock bears S65°E, 31 links, marked "T3N R10W S9BT" (now a 22" stump).
7" hemlock bears S20°W, 17 links, marked "T3N R10W S8BT" (now gone).
6" hemlock bears N33°W, 29 links, marked "T3N R10W S5BT" (now gone).

STATE PARKS CREW FOUND:

A brass cap in the center of a 30" hemlock stump.
30" hemlock stump, 2.5' high, N39°E, 19.7' to center.
22" hemlock, 2.5' high, S65°E, 21.4' to center.
5" hemlock S43°W, 12.7' to center, marked "T3N R10W S8BT."
7" spruce N60°W, 55.8' to center on slope, marked "T3N R10W S9BT RS707."
3"x3" square post 4' high, N43°E, 11.2'.
4"x4"x4" high white post 2.0' southeast of brass cap, with a corner tag by
ORE. STATE DEPT OF FORESTRY, dated 5/25/76.

WITNESSED BY:

Lee Doss
R. DePuy
C. Middleton

¼ CORNER BETWEEN SECTIONS 5 AND 4

ORIGINAL:

Set a post 3' long, 3" square, 24" in the ground for ¼ section corner, marked "1/4S" on west face from which a:

7" hemlock bears N17°W, 5 links, marked "1/4SBT."
20" hemlock bears N76°E, 46 links, marked "1/4SBT."

STATE PARKS CREW FOUND:

1" iron pipe.
21" hemlock N78°E, 31.7' to center.
Downed stump approximately N35°W, 5' distant.

The 1" iron pipe was set by an unknown party but had evidently been there a long time. The two stumps fit very closely for original bearing trees, but they are too badly deteriorated to find any scribe. We believe this corner could very easily be a perpetuation of the original.

STATE PARKS CREW SET:

6" spruce N32°E, 6.8' to center, scribed "1/4S4BT RS691" and attached yellow Parks corner tag.
8" spruce N42°W, 17.6' to center, scribed "1/4S5BT."
Set galvanized steel post with plain white paddle 2.0' east of iron pipe.

WITNESSED BY:

R. Hemmer
L. Doss
L. Boge
R. DePuy
C. Middleton
M. Swan
S. Doak

¼ CORNER BETWEEN SECTIONS 6 AND 5

ORIGINAL:

Set a post 3' long, 3" square, 24" in ground for ¼ section corner, marked "1/4S" on west face from which a: