

TILLAMOOK COUNTY SURVEYORS OFFICE

Section Corner common to sections 19 & 30 T.1S.,R.9W.,W.M.
and sections 24 & 25 T.1S.,R.10W.,W.M.

T1S
R10W R9W
S24|S19
---+---
S25|S30
1989

I set a 3" Tillamook County Brass Cap on a 5/8" iron rod inside of found 2" iron pipe with plug & round headed nail, which I found inside of an 11" cast iron Tillamook City monument case. I encased the 5/8" iron rod and 2" iron pipe in concrete.

History of Found Monument

This corner was originally set in 1857 (see Tillamook County Surveyors record G.L.O. Book 1 South Range 10 West page 5) and consisted of a post for the corner and the following BTs:

- A spruce, 32 ins. dia., bears N.47°E., 334 lks. dist. (now gone).
- A spruce, 33 ins. dia., bears N.25°W., 384 lks. dist. (now gone).

This corner was rewitnessed in Tillamook County Surveyors Rewitness book 10 at page 131 in approximately February of 1896 at which time a spruce limb was set "from gov. witnesses".<also see C.S. book S3 page 54 for same>.

In T.C.S. book S3 at page 284, dated October 28 1899, [see C.S. field notebook AMA 9 page 11 for field notes], the corner was again "established from Gov. witnesses".

In T.C.S. rewitness book 4 at page 23, in approximately February 1911, "placed 2" pipe", probably the one I found, "f.w." (from which),

- "2" pipe brs. W. 31.4'" (now gone, probably destroyed by road construction).
- "2" pipe brs. E. 30.0'" (now gone, probably destroyed by road construction).

The surveys of reference at the time of this rewitness were: book S3 page 212 (see field notebook AMA 2 page 128 for field notes), A-5572, A-4030, A-935, A-592, A-614, A-1483, A-802, A-931, B-1068, B-778, B-860, B-1151, B-1347, B-232, B-207, F-27-9,.

New Accessory

Power pole ²⁴⁸¹⁰⁰ ~~191140~~ Bears S.80°W. 39.66' to a monument spike in a triangle on the side of the pole.

Power pole ¹⁹¹¹⁴⁰ ~~248100~~ Bears N.36°37'36"E. 64.04' to a monument spike in a triangle on the side of the pole.

The interior angle was turned between the two spikes using the compass bearing of S.80°W. as a basis of bearings (angle = 136°37'36").

Location of Monument

This corner is located in the center of the left turn refuge lane on Oregon State Highway 101 at the intersection of Hadley County Road.

In the presence of Dan McNutt & Al Dvorak

April 1989

Title Allen E. Duncan, C.S.