

Oswald West Resurvey
Section 17, T3N, R10W
May 1, 1981
Page 3

Set (1975)

32" Spruce N17⁰W, 69.7', scribed "T3N R10W S17 BT".
10" Hemlock with Parks corner tag, S79⁰W, 28.9', scribed "T3N R10W S20
BT RS691".
10" Hemlock S23¹/₄⁰E, 28.8', scribed "S21 BT".

Set steel post and park boundary paddle.

E1/16 Corner Sections 17 and 20 (1981)

Set 5/8"x30" capped iron rod with aluminum cap and galvanized steel post with
boundary paddle 2.5' North.

13¹/₂" Alder N69¹/₂⁰W, 11.6' to center, bark scribed "E1/16 S17 BT".
11" Alder S38¹/₂⁰W, 25.1' to center, bark scribed "E1/16 S20 BT RS691".

1/4 Corner Sections 17 and 20 (1981)

Found 3" brass cap inside 10" tile stamped $\frac{1}{4} \frac{S17}{20}$
RS287
1979

Found 34" Spruce N62⁰W, 62.3' to center, trace of scribing visible. Yellow
Tillamook County corner tag and a white tag marked "Till. Co. Bearing Tree Do
Not Cut".

Found 50" Spruce S30⁰W, 65.9' to center, new scribe visible on root (BT)
Tillamook County yellow corner tag and a white tag marked "Till. Co. Bearing
Tree Do Not Cut".

Found steel post with white paddle and Tillamook County yellow corner tag
attached 1.5' West of monument. Neah-kah-nie mountain trail road 30'+
westerly.

Found 2" iron pipe set by Markam N55⁰43'04"E, 35.11'.
Found 1/2" iron rod with yellow plastic cap marked PLS#1205 N89⁰31'58"W,
84.16' on section line.

Removed steel post and boundary paddle marked, "OREGON STATE PARK BOUNDARY DO
NOT DISTURB" from vicinity of 2" iron pipe and reset 2' north of Tillamook
County monument.

W1/16 Corner Sections 17 and 20 (1981)

Set 5/8"x30" capped iron rod with aluminum cap and galvanized steel post with
boundary paddle 2.0' North.

12" Spruce S84⁰W, 28.7' to center, scribed "W1/16 S20 BT RS691".
36" Spruce N41⁰E, 12.3' to center, scribed "W1/16 S17 BT".

Placed Parks corner tags on both BTs.

Section Corner Sections 17, 18, 19 and 20 (1975)

Found brass cap set in concrete in a 10" tile set in 1973.

14" Fir N69⁰E, 9.2', placed Parks corner tag.
40" Fir N76⁰W, 67.0'.

Set galvanized steel post with Park boundary paddle and corner tag.

1/4 Corner Sections 18 and 17 (1975)

Found 1/2" iron pipe and 2 BTs established by Markham in 1965. Since we did not
agree with the position of this pipe, we set our own corner which bears
S45⁰35'30"E, 12.30' from the 1/2" iron pipe.