


TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 Corner Common to Sections 12 T.55.,R.11.W.,W.M.
and
Section 7 T.55.,R.10W.,W.M.



I set a 10" concrete cylinder around found B.L.M. 2 1/2" iron pipe with 3" brass cap set in 1962, (See Tillamook County Surveyors rewitness book 3 page 35).

History of found monument

I found this monument to be as described on the above said rewitness book and page and the bearing trees set and/or found at that time to now be as follows:

35" sawed spruce stump S.40*E. 19 1/2 links; (now rotten stump).
28" sawed spruce stump N.89*W. 35 1/2 links; (now rotten stump).
*21" spruce N.35*E. 39 1/2 links; (now 45" spruce I rescribed B.T and measured a new distance to a nail with a brass washer in the new face 24.38').
*16" spruce S.57*W. 46 links; (now 29" spruce I rescribed B.T and measured a new distance to a nail with a brass washer in the new face 29.28').

New Accessory

*84" hat section post North 1.5'.

*indicates Tillamook County Surveyors yellow metal location poster attached.


Monument location

This corner is located approximately 70' East of a gravel road in a stand of spruce trees.

In the presence of Dan McNutt and Al Dvorak

March 1987

Title



Allan Duncan, C.S.

