

TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 CORNER COMMON TO SECTIONS 2 AND 11 T.1N., R.10W., W.M.

T1NR10W	I found a 1" iron pipe badly rusted. (See Tillamook
S2	County Surveyors rewitmess book 2 at page 424).
1/4 ---+---	I replaced the found iron pipe with a 1 1/2" iron
S11	pipe with a 3" Tillamook County Surveyors brass cap
1991	in a 10" concrete cylinder. I layed the found iron
	pipe alongside the new monument.

History of found monument

I found this monument to be as reported on said rewitmess, and the references found and/or set at that time to now be as follows:

Original 30" hemlock S.25 E. reported in said book 2 as a 30" stub 15' high edges of rotted out face visible, no scribes; (Found at position, now a 19" snag 15' high with yellow metal location poster attached marked H.S. Williams).

17" spruce S.74 W. 23.8'; (Found, now a 36" spruce with healed face).

13" hemlock N.86 E. 26.5'; (Found, now a 25" hemlock with a partially healed face and an O.S.B.F. yellow metal location poster attached).

4"X 4"X 60" white painted cedar post 1.0' SE; (Found O.K.).

New Accessory

\*72" hat section post West 1.5'

\*indicates Tillamook County Surveyors yellow metal location poster attached.

Surveys and Rewitmesses of record

B-437	1960	Richard A. Morris RS 401
T.C.S. rewitmess book 2 at page 424	1960	Richard A. Morris RS 401
B-419	1960	Richard A. Morris RS 401
A-3361	7-77	John L. Carlich RS 287
T.C.S. rewitmess book 10 at page 68	1-4-1889	
F-40-287		Andrew M. Austin C.S.
field notebook P-16 at page 5	4-29-15	H.P. Kerr Deputy C.S.


Location of Monument

This monument is located on a steep westerly slope approximately 100' East of a creek.

In the presence of Al Dvorak and Dan McNutt

February 25, 1991

Title



*Allan E. Duncan, C.S.*

