TILLAMOOK COUNTY SURVEYORS OFFICE COURTHOUSE, TILLAMOOK, OREGON 97141

1/4 CORNER COMMON TO SECTION 24, T.1 S., R.10 W. AND SECTION 19, T.1 S., R.9 W., W. M.

1/4 T 1 S R10W | R9W XXXX XXXX S24 + S19

> LS 793 2004

I SET A 5/8" REBAR WITH A 3" DIAMETER TILLAMOOK COUNTY SURVEYOR BRASS CAP, STAMPED AS SHOWN HEREON, IN ANCHORING CEMENT AND FLUSH WITH THE PAVEMENT IN OREGON COAST HIGHWAY 101. THIS MONUMENT HAS BEEN RESET FROM TIES SET PRIOR TO OREGON DEPARTMENT OF TRANSPORTATION HIGHWAY CONSTRUCTION.

HISTORY OF FOUND MONUMENT

THE MONUMENT AS DESCRIBED ON REWITNESS CARD #211 WAS DESTROYED BY HIGHWAY CONSTRUCTION. A MONUMENT SPIKE WAS SET AS A TEMPORARY MARKER AT THE POSITION OF THE ONE-QUARTER CORNER WHICH IS BEING REPLACED BY A 3" DIAMETER BRASS CAP DESCRIBED BY THIS RESTORATION.

THE BASIS OF BEARING FOR THIS RESTORATION HAS BEEN ESTABLISHED BY HOLDING MONUMENTS 109 AND 43 FROM MAP B-2442, TILLAMOOK COUNTY SURVEY RECORDS.

SURVEYS AND REWITNESSES OF RECORD

A-69	MEDDILADA 1040	WILLIAM E ANDERSON	DE 1/05
	FEBRUARY 1940	WILLIAM E. ANDERSON	PE 1697
A-306	MARCH 1947	JACK L. SHEPPARD	LS 180
A-363	JULY 1949	WILLIAM E. ANDERSON	PE 1697
A-537	AUGUST 1952	WILLIAM E. ANDERSON	PE 1697
A-614	MAY 1955	JOHN L. CARLICH	LS 287
A-702	SEPTEMBER 1945	JACK L. SHEPPARD	LS 180
A-802	MARCH 1959	JOHN L. CARLICH	LS 287
A-852	1960	WILLIAM E. ANDERSON	PE 1697
A-869	1960	WILLIAM E. ANDERSON	PE 1697
A-931	AUGUST 1961	JOHN L. CARLICH	LS 287
A-1059	MAY 1963	JOHN L. CARLICH	LS 287
A-1226	DECEMBER 1964	JOHN L. CARLICH	LS 287
A-1559	APRIL 1968	JOHN L. CARLICH	LS 287
A-1755	JULY 1969	JOHN L. CARLICH	LS 287
A-3633	NOVEMBER 1978	C. WAYNE COOK	LS 1098
A-4079	MARCH 1980	ALLAN E. DUNCAN	LS 793
A-4517	AUGUST 1981	ALLAN E. DUNCAN	LS 793
A-5501	MARCH 1987	ALLAN E. DUNCAN	LS 793
A-5572	NOVEMBER 1987	ALLAN E. DUNCAN	LS 793
A-5759	FEBRUARY 1989	ALLAN E. DUNCAN	LS 793
A-5785	MAY 1981	C. WAYNE COOK	LS 1098
A-6193	MAY 1991	ALLAN E. DUNCAN	LS 793
A-6227	JULY 1991	C. WAYNE COOK	LS 1098
A-7071	OCTOBER 1995	ALLAN E. DUNCAN	LS 793
B-160	OCTOBER 1949	WILLIAM E. ANDERSON	PE 1697
B-207	1914	U.G. JACKSON	1 22 205 .
B-428	1960	WILLIAM E. ANDERSON	PE 1697
B-1347	JANUARY 1989	HLB & ASSOCIATES, INC.	LS 2102
B-1695	JULY 1993	TIMOTHY J. DODSON	LS 1960
B-1721	NOVEMBER 1993	HLB & ASSOCIATES, INC.	LS 2102
B-1934	OCTOBER 1995	HLB & ASSOCIATES, INC.	LS 2102
B-2175	MARCH 1998	DANIEL E. BISSEL	LS 2230
B-2239	DECEMBER 1998	C. WAYNE COOK	LS 1098
B-2299	AUGUST 1999	C. WATNE COOK	LS 1098
	1100001 1777	C. WAIND COOK	LO 1070

D 42/0	THE POST AGOO	CONTRACT TONES	T C 4505	
B-2360	MARCH 2000	TERRY L. JONES	LS 2507	
B-2442	APRIL 2001	DANIEL E. BISSEL	LS 2230	
P-17	SEPTEMBER 1990	C. WAYNE COOK	LS 1098	
P-122	MARCH 1993	HLB & ASSOCIATES, INC.	LS 2102	
P-257	MARCH 1995	C. WAYNE COOK	LS 1098	
P-290	OCTOBER 1995	HLB & ASSOCIATES, INC.	LS 2102	
P-326	MARCH 1996	HLB & ASSOCIATES, INC.	LS 2102	
P-423	DECEMBER 1997	HLB & ASSOCIATES, INC.	LS 2766	
F-4-10(F-15-11)	MAY 1929	O.S.H.D. DWG. # 1B23-19		
F-40-64	JANUARY 1948	W.W. HUDSON	PE 2747	
F-40-162	JANUARY 1952	W.W. HUDSON	PE 2747	
F-27-9	FEBRUARY 1930	O.S.H.D. DWG. # 1B26-20		
F-41-87	APRIL 1923	W.S. COATES	PE 967	
GLO - 1S 9 PAGE 78 & 1S10 PAGE 9		1857		
AMA – BOOK 8, PAGE 101		1900		
AMA – BOOK 12, PAGE 56		1 920	19 20	
AMA – BOOK 14, PAGES 90-93		1898		
BOOK S3, PAGE 90		1896		
BOOK S3, PAGES 148-151		1898		
BOOK S3, PAGES 210-211		1899		
BOOK S3, PAGES 236-237		1899		
REWITNESS BOOK 10, PAGE 139		1894		
REWITNESS BOOK 4, PAGE 23		1911		
REWITNESS C		IBER, 1970 JOHN L. CARL	ICH LS 287	
EL WEITEDD C		in in the control of the control	ACA ECEO	

NEW ACCESSORIES

SET LEAD PLUG WITH BRASS WASHER AND TACK STAMPED "T.C. SURV" IN TOP OF BOX CULVERT HEADWALL SOUTH 39° 00' 43" WEST 73.29'.

FOUND 5/8" REBAR WITH PLASTIC CAP ON EAST SIDE OF HIGHWAY 101 STAMPED "HLB & ASSOC. INC." SOUTH 87° 35' 03" EAST 84.33', SEE MAP P-423.

FOUND ODOT BRASS PLUG IN TOP OF CURB ON EAST SIDE HIGHWAY 101 STAMPED "ODOT CONTROL 43" SOUTH 38° 05' 24" EAST 68.78', SEE MAP B-2442.

FOUND 5/8" REBAR WITH RED PLASTIC CAP ON WEST SIDE OF HIGHWAY 101 STAMPED "ODOT TRAV 109" NORTH 41° 40' 46" WEST 68.44', SEE MAP B-2442.

LOCATION OF MONUMENT

THIS ONE-QUARTER CORNER IS LOCATED IN A REFUGE LANE IN THE OREGON COAST HIGHWAY 101, \pm 69 FEET WEST OF THE EAST CURB FACE AND \pm 3' FEET NORTH OF THE EASTERLY EXTENSION OF THE CENTERLINE OF GOODSPEED COUNTY ROAD.

IN THE PRESENCE OF DAN MCNUTT AND JOE JENSEN

AUGUST 12, 2004

TITLE:



REGISTERED
PROFESSIONAL
LAND SURVEYOR

CLIAN E. GUNCAM, C:S.

OREGON
JULY 14, 1967
ALLAN E. DUNCAN
793