OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: South ¼ corner of Section 13	TOWNSHIP 1 South	RANGE 10 West		
COUNTY: Tillamook		(transported to the state of th	DATE: 03-01-07	
CORNER DESIGNATION: One-quarter corner common to Sections			(Please check one)	
and 24, Township 1 South, Range 10 West, W.M.				Condition Report Only
				Not Found
			100	Renewed
				Unrecorded
				Surveyed in
			B	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness card number 296; Survey maps A-83, A-389, A-590, A-1579, A-2832, A-4055, A-4136, A-5215, A-7245, B-26, B-696, B-2180, B-2758, F-4-10, F-15-11, F-26-19, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Brass cap stamped as shown hereon. Also found a finish nail in the east side of power pole number 6N61-I12 at a distance of 1.25'				
from found comer monument.				
Monument Set (Procedures a	and Description): Not Applicable.		Sketo	ch of Found Monument:
				1/4 13
New accessories set: Set a 72" hat section post with yellow metal location tag approximately 3' East of comer monument.				
New Bearing Trees: No bearing trees are available as accessories.				
Location & Comments: This 7.5' south of the south edge of	comer monument is located approxi pavement.	mately		
Firm / Agency Address: TILLAMOOK COUN	NTY SURVEYOR'S OFFICE		•	BURVEYOR'S SEAL
Party Chief: Joe Jensen, Surv	vey Supervisor			REGISTERED PROFESSIONAL
Notes:				LAND SURVEYOR
Witness: Danny R. McNutt, T	illamook County Surveyor	•		OREGON JULY 11, 2000 DANNY R. MCNUTT 49230 RENEWAL12 - 31-

