OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

COUNTY: Tillamook COUNTY: Tillamook CONNER DESIGNATION: The one-quarter corner between Section 33, Township 2 North, Range 7 West, and Section 4, Township 1 North, Range 7 West, W.M., Tillamook County, Oregon. □ Restoration □ Rewitness □ Unrecorded □ Resteraced Out Previous Rewitnesses, Restorations and Surveys, etc: Survey map B-337; Rewitness Book 2, Page 285, Rei Book 7, Page 5, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of For upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four upright and in good condition. The cap is stamped as shown hereon. Found a rother 18" diameter Douglas Fit true (Rewitness Bo Page 285) with scribing visible at record position. We did not search for the 16" Cedar snag (Rewitness Book 2, I as set by Louis W. Arnort, P.E. 2311 in 1953. Found a 19" (13" in Rewitness Book 7, Page 5) diameter Douglas Fit tree wit face at record position. Monument Set (Procedures and Description: Not applicable. New accessories set: Set a 72" hat section post North 1.9 feet from monument. New Bearing Trees: No new bearing trees were set. Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: Till_AMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141	•
CORNER DESIGNATION: The one-quarter corner between Section 33, Township 2 North, Range 7 West, and Section 4, Township 1 North, Range 7 West, W.M., Tillamook County, Oregon. □ Restantion □ Rewitness □ Unrecorded □ Resteration □ Rewitness □ Unrecorded □ Referenced Out □ Restant surface □ Referenced Out Reset at surface □ Referenced Out Referenced Out	
Township 2 North, Range 7 West, and Section 4, Township 1 North, Range 7 West, W.M., Tillamook County, Oregon. Restoration	1
Range 7 West, W.M., Tillamook County, Oregon. Rewitness	L
Previous Rewitnesses, Restorations and Surveys, etc: Survey map B-337; Rewitness Book 2, Page 285, Ret Book 7, Page 5, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of For upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four monument. The cap is stamped as shown hereon. Found a rotten 78" diameter Douglas Fir stump (Rewitness Bo Page 285) with scribing visible at record position. Wed din not search for the 16" Cedar snag (Rewitness Book 2, Page 5) diameter Douglas Fir stump (Rewitness Book 2, Page 5) diameter Douglas Fir tree with tace at record position. Found a 24" (18" in Rewitness Book 7, Page 5) diameter Douglas Fir tree with face at record position. Monument Set (Procedures and Description: Not applicable. Sketch of Found Monument: New accessories set: Set a 72" hat section post North 1.9 feet from monument. New Bearing Trees: No new bearing trees were set. Location & Comments: This corner is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
□ Unrecorded □ Reset at surface □ Referenced Out Previous Rewitnesses, Restorations and Surveys, etc: Survey map B-337, Rewitness Book 2, Page 285, Res Book 7, Page 5, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of For upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four monument. The cap is stamped as shown hereon. Found a rotten 78" diameter Douglas Fir stump (Rewitness Book 2, Page 285) with scribing visible at record position. We did not search for the 16" Cedar snag (Rewitness Book 2, Fage 285) unit surplements as set by Louis W. Amort, P.E. 2311 in 1953. Found a 19" (13" in Rewitness Book 7, Page 5) diameter Douglas Fir tree wit face at record position. Found a 24" (18" in Rewitness Book 7, Page 5) diameter Douglas Fir tree wit face at record position. Monument Set (Procedures and Description: Not applicable. Sketch of Found Monument: New accessories set: Set a 72" hat section post North 1.9 feet from monument. New Bearing Trees: No new bearing trees were set. Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
Previous Rewitnesses, Restorations and Surveys, etc: Survey map B-337; Rewitness Book 2, Page 285, Ret Book 7, Page 5, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of For upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four upright and in good condition. We did not search for the 16" Cedar snag (Rewitness Book 2, Fage 25) diameter Douglas Fir stump (Rewitness Book 7, Page 5) diameter Douglas Fir stump with healed face at record position. Found a 24" (18" in Rewitness Book 7, Page 5) diameter Douglas Fir tree wit face at record position. Monument Set (Procedures and Description: Not applicable. Sketch of Found Monument: New Bearing Trees: No new bearing trees were set.	
Previous Rewitnesses, Restorations and Surveys, etc: Survey map B-337; Rewitness Book 2, Page 285, Res Book 7, Page 5, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of For upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four monument. The cap is stamped as shown hereon. Found a rotten 78" diameter Douglas Fir stump (Rewitness Book 2, Page 285) with scribing visible at record position. We did not search for the 16" Cedar snag (Rewitness Book 2, Page 5) diameter Douglas Fir tree with healed face at record position. Found a 24" (18" in Rewitness Book 7, Page 5) diameter Douglas Fir tree with face at record position. Monument Set (Procedures and Description: Not applicable. Sketch of Found Monument: New Bearing Trees: No new bearing trees were set. Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
Previous Rewitnesses, Restorations and Surveys, etc: Survey map B-337; Rewitness Book 2, Page 285, Ret Book 7, Page 5, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of For upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four monument. The cap is stamped as shown hereon. Found a rotten 78" diameter Douglas Fir stump (Rewitness Book Page 285) with scribing visible at record position. We did not search for the 16" Cedar snag (Rewitness Book 2, 8 as set by Louis W. Amort, P.E. 2311 in 1953. Found a 19" (13" in Rewitness Book 7, Page 5) diameter Douglas Fir tree with face at record position. Found a 24" (18" in Rewitness Book 7, Page 5) diameter Douglas Fir tree with face at record position. Monument Set (Procedures and Description: Not applicable. Sketch of Found Monument: New Bearing Trees: No new bearing trees were set. Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
Book 7, Page 5, Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of For upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four monument. The cap is stamped as shown hereon. Found a rotten 78" diameter Douglas Fir stump (Rewitness Book 2, Page 285) with scribing visible at record position. We did not search for the 16" Cedar snag (Rewitness Book 2, as set by Louis W. Amort, P.E. 2311 in 1953. Found a 19" (13" in Rewitness Book 7, Page 5) diameter Douglas Fir the with face at record position. Found a 24" (18" in Rewitness Book 7, Page 5) diameter Douglas Fir tree with face at record position. Monument Set (Procedures and Description: Not applicable. Sketch of Found Monument: New Bearing Trees: No new bearing trees were set. Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of For upright and in good condition. I placed a 12" diameter plastic cylinder and 120 pounds of concrete around the four monument. The cap is stamped as shown hereon. Found a rotten 78" diameter Douglas Fir stump (Rewitness BC Page 285) with scribing visible at record position. We did not search for the 16" Cedar snag (Rewitness Book 2, f as set by Louis W. Amort, P.E. 2311 in 1953. Found a 19" (13" in Rewitness Book 7, Page 5) diameter Douglas Fir tree with healed face at record position. Found a 24" (18" in Rewitness Book 7, Page 5) diameter Douglas Fir tree with face at record position. Monument Set (Procedures and Description: Not applicable. Sketch of Found Monument: New Bearing Trees: No new bearing trees were set. Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
Monument Set (Procedures and Description: Not applicable. Sketch of Found Monument:	found s Book 2, 2, Page 285) as Fir tree
New accessories set: Set a 72" hat section post North 1.9 feet from monument. New Bearing Trees: No new bearing trees were set. Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
New Bearing Trees: No new bearing trees were set. Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
Location & Comments: This comer is located approximately 150' South of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
of an existing logging road. Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue SURVEYOR'S SEAL SURVEYOR'S SEAL	
Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue	
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor	
REGISTERED PROFESSIONAL LAND SURVEYOR	
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor. Danny R. McNutt, PLS 49230, Tillamook County OREGON JULY 11, 2000 DANNY R. MCNUTT 49230 RENEWALIZ ST. 2008	tt

UG 2 7 2008