


**OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION:</b> 7	<b>TOWNSHIP:</b> 4S	<b>RANGE:</b> 9W	
<b>COUNTY:</b> TILLAMOOK		<b>DATE:</b> 4/13/2008	
<b>CORNER DESIGNATION:</b> WEST 1/4 CORNER		(Please Check One)	
		<input type="checkbox"/> Condition Report Only	
		<input type="checkbox"/> Restoration	
		<input checked="" type="checkbox"/> Rewitness	
		<input type="checkbox"/> Not Found	
		<input type="checkbox"/> Reset	
		<input type="checkbox"/> Referenced Out	
<b>Previous Rewitnesses, Restorations, Surveys, etc.:</b> TILLAMOOK COUNTY SURVEY B-1179, (SURVEY TO RE-ESTABLISH WEST 1/4 OF SECTION 7)			
<b>Found Monument(s) and Accessories(Condition &amp; Source):</b> FOUND 8" ABOVE GROUND IN GOOD CONDITION A 3 1/4" USFS ALUMINUM CAP ON 2 1/2" ALUMINUM PIPE, MARKED "T4S R9W / R10W 1/4 S7 1984 PLS 1305" . A 19" DOUGLAS FIR SCRIBED "1/4 S7 BT" BEARS SOUTH 62° EAST 4.6 FT.			
<b>Monument Set(Procedures &amp; Description):</b> NONE SET			
<b>Other New Accessories Set:</b>  <i>NONE</i>			
<b>New Bearing Trees:</b> 19" DOUGLAS FIR SCRIBED "1/4 S7 BT" BEARS NORTH 10° EAST 10.2 FT. TO SPIKE AT SIDE CENTER 28" DOUGLAS FIR SCRIBED "1/4 S7 BT" BEARS SOUTH 15° EAST 16.8 FT. TO SPIKE AT SIDE CENTER 28" DOUGLAS FIR STUMP SCRIBED "1/4 S7 BT" BEARS SOUTH 66° EAST 51.5 FT. TO SPIKE IN CENTER OF STUMP. ALL BEARING TREES MARKED WITH TAGS AND RED BANDS.			
<b>Location &amp; Comments:</b> CORNER FALLS ON STEEP WEST FACING SLOPE 30 FT. WEST OF THE SUMMIT OF HILL. <del>BASIC OF BEARING PER TILLAMOOK COUNTY SURVEY B-1179</del>		<b>Surveyor's Stamp</b> 	
<b>Firm/Agency:</b> STUNTZNER ENGINEERING & FORESTRY LLC			
<b>Address:</b> 2137 19TH AVENUE, FOREST GROVE OR. 97116			
<b>Party Chief:</b> JOHN HOSHALL			
<b>Notes:</b>		Office Use Only	
<b>Witness(es):</b> STEVE OLSON		