## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The East one-	TOWNSHIP 2 South	RANG	RANGE 10 West	
quarter of Section 30		<u>L</u>	I DATE: 04 00 00	
COUNTY: Tillamook				DATE: 01-08-09
The One-quarter corner common to Sections 30 and 29, Township 2			<del> </del>	(Please check one)
South, Range 10 West, W.M., Tillamook County, Oregon.				Condition Report Only
				Restoration
			B	Monument Set and Rewitness
f P-				Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: GLO original notes: Field note volume: OR-R0272, Page: 0095.0; Map A-661, Map B-78, Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Babbitt Cap, no record, disturbed and laying down on the ground. Also found a rotten 4" ax 4" white cedar post on the ground. Found a 60" diameter Spruce stump (original was a 48" diameter Spruce tree bearing S78°W 33 links [21.8'] scribed "1/4 S BT") with original "S BT" on a back cast impression. We had to use a chainsaw to cut at least 10" into the stump in order to locate the scribing. We were able to locate the original face from where this back cast was found. This is the original scribing from the 1882 GLO survey by William Wright. We did not find the scribing done by John Carlich, PLS 287 in 1956. See page 13 from Tillamook County Surveyor Field Book 2S10 Sec. 30. The Carlich scribing appears to have rotted away. We searched for and did not find the fallen 20" diameter Hemlock, which was the original GLO 8" Hemlock bearing S89°E 34 links [22.4'] scribed "1/4 S BT", that Carlich said he found on Page 13, Field Book 2S10, Tillamook County Survey Records.				
Monument Set (Procedures and Description: We reset a 3" diameter Tillamook County Brass Cap, stamped as shown hereon, by holding the GLO record bearing and distance from the face of the found scribing on the 60" spruce stump. We swung a radius of 21.8' from the face and we found the hole where the unrecorded Babbitt cap had been set. This position was found to be at the record GLO bearing of S78°W. I placed a 12" diameter plastic cylinder with 120 pounds of concrete around the set monument. The Oregon North Zone State Plane NAD 83/91 coordinate for said point is N = 639496.7607, E = 7316202.3880.			Skete	T2S R10W 1/4 S30 S29 2009
New accessories set: Set a 72" Hat Section Post North 3.0'				
New Bearing Trees set:  *19" diameter Hemlock bears N 9° W 37.9', scribed "T2SR10W1/4S30BT", tagged and painted.  *34" diameter Spruce bears S 62° E 14.7', scribed "T2S R10W 1/4 S29BT", tagged and painted.  * Indicates yellow metal location tag affixed to new bearing tree.  All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T.				
Location & Comments: This corner is located approximately 50' West of Blum Road.				
Firm / Agency Address: TILLAMOOK COUN 201 Laurel Avenue Tillamook, Oregon Party Chief: Joe Jensen, PLS	97141		ſ	REGISTERED PROFESSIONAL AND SURVEYOR
Notes: Witnesses: Danny R. McNutt,	PLS 49230, Tillamook County		Ja	Jeph V. Geusch Oregon January 10, 2006 OSEPH V. JENSEN
Surveyor,		,		60067 JEWAL DATE: 06-30- 09

